





(1) × 5		(10) × 4	 M6*20mm
(2) × 1		(11) × 6	 M6*25mm
(3) × 1		(12) × 4	 M6*35mm
(4) × 1		(13) × 4	 M6*16mm
(5) × 1		(14) × 4	 M5*18mm
(6) × 1		(15) × 10	 Φ15*Φ6*1.5mmT
(7) × 1		(16) × 1	
(8) × 1		(17) × 1	
(9) × 1L×1R			


1




2



3



4



**General Care:**

\*For clearing, wipe the surface with a damp (not wet) cloth or sponge or wipe dry with a clean lint free cotton cloth.

**Pokyny k ošetrovaniu:**

\*K čištění používejte vlhký hadřík nebo houbu, nebo ho otřete suchým nechlupatým bavlněným hadříkem.

**Pokyny k ošetrovaniu**

\*Na čistenie používajte vlhkú handričku alebo špongiu, alebo ho utrite suchou nechlpatou bavlnenou handričkou.